CODE	DESCRIPTION	NOTES	DEPT. PRICE (EX TAX)	STAFF & STUDENT PRICE
U.C.S. END OF MODEL SPECIALS				
	Macintosh SE 1MB (2 800K Drives)	[1]	2226	2478
	Macintosh SE 1MB (800K HD20)	[1]	2847	3343
	Macintosh SE 1MB (800K Rodime HD20)	[1]	2998	3384
	Macintosh SE 1MB (800K Rodime HD45)	[1]	3263	4278
	Macintosh SE 1MB (800K Rodime HD67)	[1]	3456	4646
	Macintosh SE 1MB (2 800K Drives Rodime HD20)	[1]	3058	3444
	Macintosh SE 1MB (2 800K Drives Rodime HD45)	[1]	3323	4338
	Macintosh SE 1MB (2 800K Drives Rodime HD67)	[1]	3516	4706
COMPACT MACINTOSH CPU'S				
M5880X	Macintosh Plus 1MB (800K Drive)		1689	1978
M5900X	Macintosh SE 1MB (2 FDHD Drives)	[1]	3227	3780
M0062X/A	Macintosh SE 2MB (FDHD Drive HD20)	[1]	3825	4480
M5359X	Macintosh SE/30 2MB (FDHD Drive HD 40)	[1]	5111	5987
M5361X	Macintosh SE/30 4MB (FDHD Drive HD 80)	[1]	6695	7842
MODULAR MACINTOSH CPU'S				
M5660X	Macintosh IIcx 1MB Floppy	[2]	4633	5427
M5670X	Macintosh IIcx 2MB HD 40	[2]	5439	6371
M5680X	Macintosh IIcx 4MB HD 80	[2]	7024	8228
M5333X	Macintosh II 1MB Floppy	[2]	4602	5391
M5820X	Macintosh IIx 4MB Floppy	[2]	6756	7914
M5830X	Macintosh IIx 4MB HD 80	[2]	7503	8789
M5860X	Macintosh IIx 4MB HD 160	[2]	8370	9804
MACINTOSH KEYBOARDS				
M0116	Apple Keyboard	[3]	144	168
M0115	Apple Extended Keyboard	[3]	264	309
MACINTOSH MONITORS AND ACCESSORIES				
M0400PA	Apple High-Resolution Monochrome Monitor	[4]	462	541
M0401X	AppleColor High-Resolution RGB Monitor	[5]	1144	1340
M0402X	Apple Two Page Monochrome Monitor	[6]	2091	2449
M0404X	Apple Macintosh Portrait Display	[7]	1074	1258
M0211PA	Macintosh II Video Card		582	682
M0504	Macintosh II 1 Bit Video Card		177	208
M0260	Macintosh II Two Page Monochrome Video Card		595	697
M0119X	Macintosh II Portrait Display Video Card		595	697
M0213	Macintosh Video Card Expansion Kit	[8]	228	268
M0403	Apple Universal Monitor Stand		114	134
MACINTOSH MEMORY EXPANSION				
M0218	Apple 1MB Memory Expansion Kit	[9]	526	616
M0219	Apple 2MB Memory Expansion Kit	[10]	1055	1236
M0707	Apple 4MB Memory Expansion Kit	[11]	2109	2471

Notes: [1] Keyboard sold separately.
[2] Monitor and keyboard sold separately.
[3] Not suitable for Macintosh Plus.
[4] Requires Macintosh II Video Card (M0211PA) or 1 Bit Video Card (M0504).
[5] Requires Macintosh II Video Card (M0211PA).
[6] Requires Macintosh II Two Page Monochrome Video Card (M0260).
[7] Requires Macintosh II Portrait Display Video Card (M0119X).
[8] For use with Video Cards. Not suitable for 1 Bit Video Card (M0504).
[9] 256K SIMMs (4). Not suitable for Mac Plus or SE.
[10] 1MB SIMMs (2). Suitable for Compact Mac only.
[11] 1MB SIMMs (4). Not suitable for Compact Mac.

CODE	DESCRIPTION	NOTES	DEPT. PRICE (EX TAX)	STAFF & STUDENT PRICE
3RD PARTY APPLE PRODUCTS				
	APPLE MODEM CABLE		52	61
	APPLE SCREEN FILTERS		25	30
	M/S MOUSE PAD		8	10
	SWIVEL BASE		23	27
	SECURITY KIT (128K->PLUS)		23	27
	SECURITY KIT (Mac SE, Mac 11)		23	27
	MAC BATTERIES		3	4
	CARRY BAGS		78	92
	2MB RAM UPGRADE		626	734
	4MB RAM UPGRADE		1251	1469
MISCELLANEOUS ACCESSORIES/SUPPLIES				
A9M0103	Apple MIDI Interface		119	139
M2705	AppleCD SC Caddy - (Box/5)		63	74
MACINTOSH SOFTWARE				
M0681ZP/A	System Software Update		66	
M0556/A	HyperCard	[1]	66	
M0524	68000 Development System		198	
MACINTOSH UPGRADE EXCHANGE MODULES				
M2516X	400K to 800K Disk Drive & 128K Rom Upgrade		239	280
M2518	128K to Macintosh Plus Logic Board Upgrade	[2]	898	1051
M2518	512K to Macintosh Plus Logic Board Upgrade	[2]	580	680
M0271PA	Macintosh IIx Logic Board Upgrade		2091	2449
M0244B	Macintosh II FDHD Upgrade	[3]	595	697
LASER PRINTERS				
M6200X	LaserWriter II SC	[1]	3586	4200
M6210X	LaserWriter II NT	[2]	5679	6652
M6215X	LaserWriter II NTX	[2]	7773	9104
LASER PRINTER MEMORY EXPANSION				
M6005	LaserWriter II NTX 1MB Expansion	[3]	526	616
M6006	LaserWriter II NTX 4MB Expansion	[3]	2109	2471
LASER PRINTER UPGRADES				
M0191	LaserWriter PostScript Upgrade	[4]	598	700
M0191	LaserWriter Plus PostScript Upgrade		358	420
M6009X	LaserWriter II SC to NT Upgrade		2389	2799
M6004X	LaserWriter II SC to NTX Upgrade		5081	5952
M6004X	LaserWriter II NT to NTX Upgrade		2988	3500
LASER PRINTER ACCESSORIES				
M0230	LaserWriter A4 Cassette	[5]	65	76
M0231	LaserWriter B5 Cassette	[5]	65	76
M0180	LaserWriter Toner Cartridge		129	151
M0138	LaserWriter II A4 Cassette		97	113
M0140	LaserWriter II B5 Cassette		97	113
M0141	LaserWriter II Envelope Cassette		97	113
M6002	LaserWriter II Toner Cartridge		129	151

Notes: [1] Requires 1MB CPU and Dual Drive as a minimum.
[2] Requires 800K Disk Drive. If not present, install M2516X first.
[3] Suitable for use with Macintosh II Logic Board only.

Notes: [1] Requires SCSI cables.
[2] Requires LocalTalk cabling which is dependent on configuration. See cabling guide.
[3] Not suitable for use in CPUs.
[4] Updates LaserWriter or LaserWriter Plus to optimised PostScript LaserWriter Plus.
[5] Suitable for LaserWriter or LaserWriter Plus only.

CODE	DESCRIPTION	NOTES	DEPT. PRICE (EX TAX)	STAFF & STUDENT PRICE
IMPACT PRINTERS & ACCESSORIES				
A9M0320Z	Imagewriter II Printer		637	746
A9G0432	Imagewriter II sheetfeeder		248	291
A9M0340B	ImageWriter LQ Printer	[2]	1848	2165
A9G0340	ImageWriter LQ Sheetfeeder		364	426
A9G0341	ImageWriter LQ Expansion Bin	[3]	218	255
A9G0343	ImageWriter LQ Envelope Attachment	[4]	66	78
A9B0314	ImageWriter II/LQ LocalTalk option		228	268
SCANNER				
A2P0337	Apple Scanner	[5]	2091	2449
DISK DRIVES				
A9M0106PA	Apple 3.5 Drive		427	500
A9M0110	Apple PC 5.25 Drive	[9]	470	550
M0234	Macintosh II PC Drive Card	[10]	162	190
M0235	Macintosh SE-Bus Drive Card	[10]	162	190
M0136	Macintosh Internal 800K Drive	[11]	327	384
M0247X	Macintosh Internal FDHD 1.4MB Drive	[12]	427	500
M0216/A	Macintosh Internal 20SC Hard Disk	[13]	956	1120
M0269	Macintosh Internal 40SC Hard Disk	[13]	1287	1507
M0283X	Macintosh IIcx Internal 40SC Hard Disk		1287	1507
M0270	Macintosh Internal 80SC Hard Disk	[14]	1915	2243
M0284X	Macintosh IIcx Internal 80SC Hard Disk		1915	2243
M0267	Macintosh Internal 160SC Hard Disk	[14]	2972	3482
M2620/A	Apple Hard Disk 20SC	[15]	1088	1275
M2644/A	Apple Hard Disk 40SC	[15]	1418	1662
M2688/A	Apple Hard Disk 80SC	[15]	2079	2436
M2666	Apple Hard Disk 160SC	[15]	3071	3598
M2640X	Apple Tape Backup 40SC	[5]	1584	1856
M2700X/A	AppleCD SC	[5]	1407	1648
	INTERNAL RODIME HD20		772	906
	INTERNAL RODIME HD45		1036	1216
	INTERNAL RODIME HD67		1229	1443
	INTERNAL RODIME HD100		1678	1970
	INTERNAL RODIME HD140		2008	2357
	INTERNAL COBRA HD45		1130	1327
	INTERNAL COBRA HD70		1426	1674
	INTERNAL COBRA HD100		1839	2159
	INTERNAL COBRA HD200		2675	3140
	EXTERNAL RODIME HD20		957	1123
	EXTERNAL RODIME HD45		1385	1625
	EXTERNAL RODIME HD67		1542	1810
	EXTERNAL RODIME HD100		1868	2192
	EXTERNAL RODIME HD140		2215	2600
	EXTERNAL COBRA HD45		1418	1665
	EXTERNAL COBRA HD70		1711	2009
	EXTERNAL COBRA HD100		1968	2310
	EXTERNAL COBRA HD200		2969	3486

Notes: [2] Please order with no charge Accessory Kit A9C0109X/A.
[3] 2 bins in addition to sheetfeeder, which is required.
[4] Requires Sheetfeeder.
[5] Needs SCSI Cables.
[8] Requires Apple 5.25 Drive. (A9M0107Z)
[9] For use with Macintosh SE or Macintosh II drive card.
[10] Requires Apple PC 5.25 Drive (A9M0110). Not suitable for SE/30.
[11] Macintosh II only.
[12] Macintosh IIx only. For Macintosh II, purchase upgrade (M0244B).
[13] Suitable for Macintosh II and IIx only; (3.5" drive)
[14] Suitable for Macintosh II and IIx only; (5.25" drive)
[15] Includes SCSI Cable (M0206) and Terminator (M0209).

CODE	DESCRIPTION	NOTES	DEPT. PRICE (EX TAX)	STAFF & STUDENT PRICE
CABLES AND CONNECTORS				
A2C0312	Macintosh XL / LISA Peripheral - 8 cable		30	35
M0196	Macintosh Peripheral- 8 cable	[3]	30	35
M0197	Apple System Peripheral-8 Cable		30	35
M0199	Macintosh Peripheral Adaptor Cable		30	35
M0206	SCSI System Cable		66	78
M0207	SCSI Peripheral Interface Cable	[4]	63	74
M0208	SCSI Cable Extender	[5]	63	74
M0209	SCSI System Cable Terminator		63	74
M2065	LocalTalk Connector Kit (DB9)		65	76
M2066	LocalTalk Cable Kit - 10M		63	74
M2068	LocalTalk System Connector Kit		65	76
M2069	LocalTalk Cable Kit - 25M		126	147
M2070	LocalTalk Custom Wiring Kit - 100M		790	926
COMMUNICATIONS PRODUCTS				
A9U0004	Apple Personal Modem Plus	[7]	592	694
M0405	EtherTalk Interface card	[8]	1190	1394
M0521/B	MacTerminal		117	
M0548/B	AppleShare File Server		923	
M0576	AppleShare Print Server		394	
M0673/B	AppleShare PC Workstation Software		165	
M0697	Inter•Poll Network Admin Utility		132	
M2313B	AppleShare LocalTalk Bundle	[9]	493	578

Notes: [3] Connects ImageWriter II to Macintosh 128/512K.
[4] Connects 2 SCSI devices together.
[5] Connects with a SCSI cable to extend length.
[7] Communication software included. Please specify CPU when ordering.
[8] Macintosh II and IIx only.
[9] Requires LocalTalk Connector Kit (DB9). Now bundled with M0673/B

A/UX				
AM0691	A/UX w/Apple Hard Disk 80SC	[1]	3038	3560
AM0692	A/UX w/Macintosh Internal 80SC Hard Disk	[1]	2939	3443
AM0690	A/UX on Apple Tape 40SC Cartridges	[1] [2]	1148	1345
A/UX ACCESSORIES				
M0221	PMMU Chip		592	694
M0709	X Windows Software version 11.3		394	
M0333PA/A	A/UX Accessory Kit		100	117
AM0676	A/UX Manual Set		919	1077
A/UX LICENSES				
M8150PA	5 Unit "Right to Copy"	[3]	2392	2804
M8153PA	10 Unit "Right to Copy"	[3]	4761	5581
M8160PA	25 Unit "Right to Copy"	[3]	11553	13543
M8165PA	50 Unit "Right to Copy"	[3]	22880	26821
M8167PA	100 Unit "Right to Copy"	[3]	45520	53361
M8170PA	250 Unit "Right to Copy"	[3]	113485	133032
A/UX SUPPORT PRODUCTS				
ATS2101	A/UX Hotline - 5 Hours		1728	2025
ATS2102	A/UX Hotline - 15 Hours		4863	5700

Notes: [1] Requires Macintosh IIx or IIcx, or Macintosh II with mimimum 4MB and PMMU. Price includes A/UX Accessory Kit and 2 hours introductory support.
[2] Require Apple Tape Backup 40SC and minimum 80MB Hard Disk.
[3] Requires approval of Apple Product Marketing prior to sale.